Highlights

- Low temperature limits: FA1: 475°C (887°F), FA2: 250°C (482°F)
- High accuracy
- High optical resolution up to 100:1
- Focus distances down to 100 mm (3.9 in)
- · Fast response time down to 10 ms
- Fiber optic assembly withstands 200°C (392°F), optional up to 315°C (600°F)
- 0/4 20 mA analog output
- RS485 serial output; networkable (up to 32 sensors)
- · Advanced signal processing
- Background radiation compensation
- Programmable relay output: dual temperature setpoints and failsafe alarm
- Marathon DataTemp® software for remote configuration and monitoring

Marathon Series

FA

Datasheet




Cutputs 0/4-20 mA; RS485, 2-wire or 4-wire, networkable to 32 sensors Relay, 48 V, 300 mA, response time < 2 ms Power Supply 24 VDC ± 20%, 500 mA

	30.110.000.000.000.000.000.000.000.000.0
General Specification	s
Environmental Rating	IP65 (IEC529) / NEMA-4
Ambient Temperature	
Optical head	0 to 315°C (32 to 600°F)
Fiber cable	0 to 200°C (32 to 392°F)
	optional up to 315°C (600°F)
Electronics housing	0 to 50°C (32 to 122°F)
	with cooling platform up to 150°C (302°F)
Storage Temperature	
Electronics housing	-20 to 70°C (-4 to 158°F)
Relative Humidity	10 to 95%, non-condensing
Shock	
Electronics housing	IEC 68-2-27
Vibration	
Electronics housing	IEC 68-2-6
Weight	
Optical head	100 g (3.5 oz)
Electronics housing	710 g (25 oz)
Fiber Cable Protection	rated to 200°C (392°F), stainless steel
	armour, Viton coated, IP65 / NEMA-4,
	provision for conduit to protect fiber cable


475 to 900°C (887 to 1652°F)
800 to 1900°C (1472 to 3452°F)
1200 to 3000°C (2192 to 5432°F)
250 to 800°C (482 to 1472°F)
400 to 1700°C (752 to 3092°F)
1.0 µm (Si detector)
1.6 µm (InGaAs detector)
\pm (0.3% T _{meas} +2°C), T _{meas} in °C
± 1°C
± 0.05°C
±1°C
10 ms (95%), selectable to 10 s
0.10 to 1.00 in 0.01 increments
Peak hold, valley hold, averaging

Dimensions

Electronics Housing



Optical Head








Accessories

The models include a mounting nut, adjustable mounting bracket, an operator's manual and the DataTemp Software. Additional accessories are available:

- Furnace rooftop mounting/purging system available with either flange (XXXFORFMF) or gravity-held base (XXXFORFMC)
- Stainless steel air-purge collar for optical head with integrated stainless steel sighting tube (XXXFOHAPA)
- Fiber-optic sighting tube conduit accessory, L 300 mm (12 in), Ø 32 mm (1.3 in), (XXXFOSTCA)
- 24 VDC / 1.3 A power supply with universal 100 / 240 VAC input (XXXSYSPS)
- USB/RS485 converter (XXXUSB485)
- Aiming-light (battery powered) for fiber optic front end including adapter to FA fiber cable (XXXFAFAL)
- Terminal block (XXXMATB)
- Terminal block with 24 VDC power supply and enclosure (RAYMAPB)

76 (3.0) Adjustable - 38 (1.5) -51 (2.0) Bracket (XXXFOMB) 38 (1.5) (2.0)51 (2.0) R 35 (1.38) mm (inch) (0.25)

Air Purge Collar (XXXFOHAPA)





Furnace rooftop mounting/purging system available with either flange (XXXFORFMF) or gravity-held base (XXXFORFMC)

Optical Specifications

Optical Resolution D : S1

FA1A ²	20:1
FA1B	100:1
FA1C	100 : 1
FA2A ²	20 : 1
EASE	40 - 1

Focus Distances

Standard Focus

Close Focus 1 100 mm (3.9 in) Close Focus 2 300 mm (12 in)

1 at 95% energy, D: Distance between sensor and object, S: diameter of spot size

Options

Options must be specified at time of order.

- Fiber optic cable lengths: 1, 3, 6, 10 m (3, 10, 20, 33 ft)
- Manufacturer's Calibration Certificate based on certified probes traced on national standards, e.g. DAkkS (XXXFACERT)
- Laser Sighting (...L), only for FA1A/FA2A
- Electronics Housing Cooling Platform (...W)
- 12-pin DIN quick disconnect connector on electronics box (...C)
- High Temperature Fiber Cable (...H), rated to 315°C, not available on FA2, option excludes Viton coating and IP65

Fluke Process Instruments

Americas

Santa Cruz, CA USA Tel: +1 800 227 8074 (USA/Canada only) +1 831 458 3900

solutions@flukeprocessinstruments.com

EMEA

Berlin, Germany Tel: +49 30 4 78 00 80 info@flukeprocessinstruments.de

Beijing, China Tel: +86 10 6438 4691 info@flukeprocessinstruments.cn

Japan

Tokyo, Japan Tel: +81 03 6714 3114 info@flukeprocessinstruments.jp

Asia East and South

India Tel: +91 22 2920 7691 Singapore Tel: +65 6799 5578 sales.asia@flukeprocessinstruments.com







Worldwide Service

Fluke Process Instruments offers services, including repair and calibration. For more information, contact your local office.

www.flukeprocessinstruments.com

© 2016 Fluke Process Instruments Specifications subject to change without notice. 13/2016 - Rev. F4, 59601







² available with laser sighting